


3600W DIAMOND CORE DRILL

EN

EXPLOSIVE VIEW OF WD030913600



PART LIST OF WD030913600

NO	DESCRIPTION	Q'TY	NO	DESCRIPTION	Q'TY
1	Spindle	1	40	Rotor	1
2	O ring	2	41	Insulation washer	1
3	Circlip	1	42	Air guiding plate	1
4	Dust cover	1	43	Screw	2
5	Bearing 6205	2	44	Stator	1
6	Gear box	1	45	Screw	6
7	Wool column	1	46	Carbon brush cover	2
8	Screw	1	47	Carbon brush	2
9	Shaft seal	1	48	Washer	2
10	Gear	1	49	Screw	2
11	Flat key	2	50	Brush holder	2
12	Circlip	1	51	Brush spring	2
13	Bearing 6201	2	52	Housing	1
14	Pinion shaft	1	53	Screw	4
15	Gear	1	54	O ring	1
16	Flat key	1	55	Bearing holder	1
17	Bearing 6201	2	56	Screw	6
18	Pinion shaft	1	57	Rear cover	1
19	Circlip	1	58	Screw	4
20	Friction plate	2	59	Switch with circuit protector	1
21	Bush	1	60	Switch box	1
22	Gear	1	61	Cable strain relief	1
23	Circlip	1	62	Cable and plug	1
24	Disk spring	2	63	Clamp	1
25	Nut	1	64	Screw	1
26	Screw	4	65	Wire connector	1
27	Bearing 6902		66	Cover	1
28	Shaft seal	1	67	Base plate	1
29	Bush	2	68	Nut	4
30	Gasket	1	69	Bolt	4
31	Middle cover	1	70	Screw	2
32	Pin	1	71	Washer	6
33	Bearing 6200	1	72	Carrying handle	1
34	Pipe joint	1	73	Nut	4
35	Hose	1	74	Screw	4
36	Quick coupling	1	75	Screw	4
37	Water valve	1	76	Cover	1
38	Screw	1	77	Shaft	6
39	Bearing 6202	1	78	Roller	12