


EXPLOSIVE VIEW OF WD012111500



PART LIST OF WD012111500

NO	DESCRIPTION	Q'TY	NO	DESCRIPTION	Q'TY
1	Hexagon head bolt	1	26	Screw	1
2	Outer flange	1	27	Base plate	1
3	Inner flange	1	28	Washer	1
4	Cover of gear box	1	29	Lock knob of cutting depth	1
5	Gasket	1	30	Rotor	1
6	Steel sleeve	1	31	Washer	1
7	Felt washer	1	32	Bearing 608	1
8	Washer	1	33	Bearing sleeve	1
9	Bearing 6002	1	34	Fan baffle	1
10	Circlip	1	35	Screw	2
11	Output shaft	1	36	Stator	1
12	Woodruff key	1	37	Handle cover	1
13	Gear	1	38	Dust proof cap of switch trigger	1
14	Bearing 606	1	39	Dust proof cap of lock-on button	1
15	Hexagon socket screw	5	40	Switch	1
16	Gear box	1	41	Housing	1
17	Fan guide	1	42	Screw	4
18	Bearing sleeve	1	43	Fan guide	1
19	Nut	1	44	Cable clamp	1
20	Pinion	1	45	Screw	2
21	Woodruff key	1	46	Cable protector	1
22	Bearing 629	1	47	Cable and plug	1
23	Washer	1	48	Brush holder	2
24	Bevel locking bolt	1	49	Carbon brush	2
25	Nut	1	50	Cap of carbon brush	2